
INSTALLATION STEPS:

В

- AFFIX BOTTOM TRACK TO FLOOR USING APPROPRIATE QUANTITY OF ANCHORS OR SCREWS.
- 2. AFFIX T-KNEE WALL SUPPORT BRACKET ASSEMBLY TO TRACK AND FLOOR USING FOUR (4) ANCHORS, TWO (2), OR ONE (1) ANCHORS AS NEEDED FOR LOAD CONDITIONS. FOLLOW ANCHOR MANUFACTURER'S INSTALLATION INSTRUCTIONS.
- 3. AFFIX ONE STUD (SHORT) TO T-KNEE WALL SUPPORT BRACKET ASSEMBLY WITH AT LEAST THREE (3) ROWS OF TWO (2) SCREWS IN THE TOP, MIDDLE, & BOTTOM.
- 4. AFFIX TOP AND BOTTOM TRACKS TO STUDS USING TWO (2) SCREWS.



T-KNEE WALL SUPPORT BRACKET ASSEMBLY



Telling[®] Industries, LLC.
THE LEADER IN METAL

THE LEADER IN METAL FRAMING INNOVATION

www.BuildStrong.com 866- FRAME-TI (372-6384)

This drawing serves as a reference only and should not substitute the expertise of a qualified architect or engineer. It is intended to aid in the development of cold-formed steel framing construction details. A thorough evaluation and approval by a qualified architect or engineer are required.

В

4