



This symbol can be used for ironer model F32118-3 all heat types



This symbol can be used for ironer model F32130-3 all heat types



This symbol can be used for ironer model F32138-3 all heat types

Legend of connection symbols

- | | | | |
|---|-----------------------------|---|--|
| ⊕ | Main electrical connection | ⊕ | Compressed air inlet connection |
| ⊕ | Gas inlet connection | ⊕ | Steam inlet connection (optional on washers) |
| ⊕ | Exhaust vent connection | ⊕ | Steam condensate return connection |
| ⊕ | Cold water inlet connection | | |

All clearances shown are minimum recommended