



NOTCHED AND  
REMOVED

CR-AX4  
I/S CORNER

GAP TO BE  
FILLED WITH  
APPROVED  
SEALANT

CR-AX6  
HORZ / VERT

18E INSIDE CORNER, OPTION 5