



Standard Lead Lined Wood Door is not fire rated. Fire Rating up to 20 Minutes is available at additional cost and when specified upon ordering.

a-fabco, inc. * 800-330-5323

Gibsonton, FL 33534

DRAWN BY: Allen Lynch

CLIENT : ARCAT AutoCAD Downloads

PROJ: X-ray & Radiation Protection - Sec. 13090

SUBJ: Lead Door Core Construction Detail

DATE : December 11, 2008