



SUNNY SIDE
100° F


ZEROLOC CONTINUOUS
CORNER PANEL



FREEZER
-20° F



SHADED SIDE
70° F



THIS DETAIL IS NOT RECOMMENDED DUE DIFFERING RATES OF EXPANSION AND CONTRACTION (THERMAL BOWING) FROM ONE SIDE OF THE CORNER TO THE OTHER. A SEVERE TEMPERATURE DIFFERENTIAL (ΔT) FROM ONE EXTERIOR SIDE OF THE CORNER TO THE OTHER COULD RESULT IN 'KINKING' OF THE METAL SKIN AT THE CORNER CONNECTION.

EXTERIOR CONTINUOUS CORNER PANEL DETAIL
(NOT RECOMMENDED)