



NEW PENETRATION IN EXISTING WALL AT PANEL JOINTS

SEE DETAIL CI-CF-PEN-4 FOR SEALANT LOCATIONS