



Deep-Dek® 4.5 ON LOAD BEARING WIDE FLANGE BEAM
INTERIOR CONDITION